

May 24, 2022

Kleinfelder Project No.: 20200528.001A

Costco Wholesale c/o Mr. Travis Morton, Associate MG2 1101 Second Avenue, Suite 100 Seattle, Washington 98101

Subject: Revised Special Inspection Final Letter – Temporary Occupancy

Costco Wholesale Building 5 Pedestrian Skybridge B3-B5

755 Lake Drive

Issaquah, Washington 98027

CW17-1048-03

Building Permit No. BLD18-00374

Dear Mr. Morton:

This inspection letter documents that Kleinfelder performed Special Inspection and materials testing services for the Costco Wholesale Building 5 Skybridge project as required by the project plans, specifications, and applicable sections of the International Building Code (IBC). Specifically, we performed the following inspections:

- Structural Steel and Welding Inspection;
- Reinforced Concrete Inspection and Testing;
- Architectural veneers / wraps for the columns supporting the skybridge; and,
- Curtain Walls on the Skybridge Structure.

Kleinfelder's WABO certified special inspectors and testing professionals performed the above listed inspections and testing services between the dates of August 2, 2021 and May 23, 2022. Based upon our inspector's observations/inspections and materials test data reports of these work elements and written reports regarding this work, it is our professional opinion that the above inspected work was performed, to the best of our knowledge, in accordance with the approved plans, specification, and the applicable workmanship provisions of the International Building Code.

The piles that support this structure were installed a separate permit number, BLD19-00297. Kleinfelder issued a separate final letter for that permit on October 10, 2021.

LIMITATIONS

Test results or special inspections and observations reported are those existing at the time of our services and may not be the same or comparable at other times. As our client, please recognize that construction monitoring is a technique employed to reduce risk of problems arising during construction. Provision of construction monitoring by Kleinfelder personnel is not insurance, nor does it guarantee construction of any type. Even with diligent monitoring, some construction defects may have been missed. In all cases, the contractor shall retain sole responsibility for the deficiencies or omissions, regardless of when they are found. We do not undertake the guarantee of construction or production of a completed project conforming to the project plans and specifications.

This work was performed in a manner consistent with the level of care and skill ordinarily exercised by other members of Kleinfelder's profession practicing in the same locality, under similar conditions, and at the date the services are provided. Our conclusions, opinions, and recommendations are based on a limited number of observations and data. It is possible that conditions could vary between or beyond the data evaluated. Kleinfelder makes no other representation, guarantee or warranty, express or implied, regarding the services, communication (oral or written), report, opinion, or instrument of service provided.

CLOSURE

We trust that this report serves your needs at this time. If you have questions regarding our professional services or need additional information, please contact our office at (425) 636-7900.

Respectfully submitted,

KLEINFELDER, INC.

Jason Williams CoMET Manager

WABO Field Supervisor

Marcus Byers, PE, P.Eng Principal Geotechnical Engineer Senior Project Manager